

Play Equipment:
 Metal Climber
 Bars
 Posts
 6 Swings
 TB
 VB


2.8 Acres
 Condem. in 1910
 \$23,851 = '08 BF.
 "...for park + parkway purposes."
 801 E. 50th St.

1st enclosed play field - wire fence w/ gates
 and locks - 1911
 Shelter House (1951) \$7,055 = Cum. Res. + St. Fds.
 replaced original one built in 1911.
 Community clubs: \$1,000 = 1943

141

UNIVERSITY P.G.


091676



141

YEAR OF IMPROVEMENT: 1983
 COST OF IMPROVEMENT: \$70,935.15
 DESIGNER: CONSERVATION COMPANY
 CONTRACTOR: LANDSCAPE SERVICES INC.

01 06 86



1st enclosed play field - wire fence w/ gates and locks - 1911

Shelter House (1951) \$7,055 = Cum. Res. + St. Fds. replaced original one built in 1911.

Community clubs: \$1,000 = 1943

2.8 Acres

Condem. in 1910

\$23,851 = '08 BF.

"... for park + parkway purposes."

801 E. 50th St.

141

UNIVERSITY P.G.

SHEET 2 OF 2

091676